

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

REPLACEMENT SHEET




Fig. 1




Fig. 2




Fig. 3




Fig. 4

REPLACEMENT SHEET




Fig. 5





Fig. 6



REPLACEMENT SHEET




Fig. 5a



REPLACEMENT SHEET




Fig. 7




Fig. 8




Fig. 9



REPLACEMENT SHEET




Fig. 10



REPLACEMENT SHEET




Fig. 11




Fig. 12




Fig. 13




Fig. 14



REPLACEMENT SHEET




Fig. 15



REPLACEMENT SHEET





Fig. 16





REPLACEMENT SHEET





Fig. 17



REPLACEMENT SHEET





REPLACEMENT SHEET





Fig. 19



REPLACEMENT SHEET





Fig. 20



REPLACEMENT SHEET



Power in kW	Electrical efficiency in %, 120°C	Electrical efficiency in %, -120°C
152	91,89	97,35
167	92,62	97,59
182	93,24	97,79
197	93,76	97,96
213	94,20	98,11
228	94,59	98,23
243	94,93	98,34
258	95,23	98,44
273	95,49	98,53
288	95,73	98,61
304	95,94	98,68
319	96,14	98,74
334	96,31	98,8
349	96,47	98,85
364	96,62	98,9
379	96,75	98,94
395	96,88	98,98
410	97,00	99,02
425	97,10	99,05
440	97,20	99,09
455	97,30	99,12

Fig. 21